

High pressure sensors

<https://ehle-hd.com/en/product/high-pressure-sensors/>




The **high pressure sensors** are used for overpressure measurements up to 25 bar. The sensors are equipped with a compressed air quick connector type 25.

Features

Special features:

- for external connection with AIR-PIT-Devices
- with 5 m of connecting supply, cable oil-hard and hardwearing
- stable transport suitcase
- for high-pressure measurements up to 25 bar overpressure
- pressure connection with plug-in sleeve type 25
- A/D converter: integrated, 16 bits (65536 MW)
- Resolution: < 0.4 mbar (technical)

Attributes

Image	SKU	Productname	Attributes	LxWxH & Weight
	S2004143	High pressure sensor - 0 to 25 bar	measuring range: 0 to 25 bar (0 to 362 psi)	300 × 400 × 110 mm 0.10